

MULTICS OPERATING STAFF NOTE

MOSN-264

TO: Distribution
FROM: D. L. Jones
DATE: February 28, 1973
SUBJECT: MOSN Index for February

This MOSN obsoletes MOSN-264.

Please note that only those MOSN's that have not been obsoleted are listed in this index.

<u>No.</u>	<u>Title</u>	<u>Published</u>
34	Multics Configuration Dependence	02/18/69
39	Trouble While Doing A Save	04/24/69
45	Multics Information, Complaint and Help Service	06/11/69
51	Updating the Recorded Message on Data Switch Extension 1301	06/26/69
87	Setting the Calendar Clocks (operations only)	10/30/69
111	Memory Read Procedure for Parity Errors	01/29/70
118	Tours of the GE-645 Machine Room	03/09/70
119	Creation and Maintenance of Restore Tape for Development Machine Testing	03/12/70
120	Date Deletion of Card Input	03/14/70
132	Operation with Varying Multics Configurations	06/01/70
134	DSU-270 Errors	05/18/70
140	Tape Mounting Procedures	08/07/70
147	VFU Printer Tape	01/26/70
149	Dump w*, Save and Restore Deaths	02/02/71
156	Complete Dumps	02/23/71
157	Incremental Backup	02/23/71

<u>No.</u>	<u>Title</u>	<u>Published</u>
160	Revision of MOSN-141 (Use of Dynamic Reconfiguration in Multics)	03/09/71
169	New Command "set_timax"	04/29/71
171	2-Channel Operation of the DSU-270	04/29/71
181	Errors While Processing On-Line Dumps	06/14/71
190	Static File Migration	08/02/71
207	On-Line Processing of Multics "FDUMPS"	10/26/71
209	Instructions for operating the Initializer and Answering Service	10/27/71
210	Non-Obvious Multics Switch Settings	10/27/71
216	Operation of the IOM	12/15/71
219	Retrievals	12/17/71
221	Development Machine Scheduling	01/18/72
222	Instructions for Operating the Datanet-355	01/21/72
224	Interrupt Cell Assignments	02/10/72
225	Procedure for Performing SAVE of DSU-270 On the Development Machine	02/14/72
229	Drum/Disk Error and Status Codes	03/03/72
230	BOS Configuration Deck	03/03/72
231	Operator's Guide to BOS	04/11/72
232	New 355 Dumper	03/14/72
233	Instructions for Operating the Multics ARPA Network Software	03/17/72
234	IMP Configuration Cards	03/17/72
235	Additions to BOS Configuration Deck for Tapes	03/17/72
236	New Tape Drive Recovery Procedure	03/17/72
239	New Drum DIM	03/17/72

<u>No.</u>	<u>Title</u>	<u>Published</u>
240	Processor Data Switches Used by Multics, et. al.	03/20/72
241	BOS Runcom Files	03/20/72
242	Problems Returning to BOS	03/27/72
245	Simulating BOS PATCH for PML Systems	04/28/72
246	Operation of the Multics Salvager	04/24/72
247	The DEBG Configuration Card	05/08/72
248	Change to BOS Toehold	05/10/72
250	New PRPH Card for Printer	06/12/72
251	355 Dumper/Patcher	06/26/72
253	New DSU-170 DIM	07/10/72
254	Initializer Messages	07/17/72
255	Current Channel Assignment for Peripheral Devices	07/19/72
256	Device Identifications Used on Configuration Cards	07/21/72
258	Use of the Bulk Store	10/31/72
261	Service System "lines" File	12/21/72
263	I/O Daemon Operation	01/11/73
264	MOSN Index for February	02/28/73

3

1

1